

**ZPMV2.E5299**  
**Wiring, Printed - Component**


**WESTAK INC**  
1225 ELKO DR  
SUNNYVALE, CA 94089 USA

E52909

Type	Cond Width		Cond Thk mic(mil)	SS/ DS/ DSO	Max Area Diam mm(in)	Solder		Max		Meets UL796 UL796 UL796	C T I	
	Min mm(in)	Min Edge mm(in)				C	sec	Oper Temp C	Flame Class			DSR
<b>Multilayer printed wiring boards.</b>												
<b>8A*</b>	0.13 (0.005)	0.3 (0.012)	16.5 (0.65)	DS	76.2 (3.0)	260	20	105	V-0	All	-	
<b>8B*</b>	0.13 (0.005)	0.3 (0.012)	16.5 (0.65)	DS	76.2 (3.0)	260	20	120	V-0	All	-	
<b>8C</b>	0.05 (0.002)	0.15 (0.006)	8.1 (0.32)	DS	76.2 (3.0)	274	20	130	V-0	All	3	
<b>8D</b>	0.05 (0.002)	0.15 (0.006)	8.1 (0.32)	DS	76.2 (3.0)	274	20	130	V-0	All	3	
<b>8F</b>	0.05 (0.002)	0.05 (0.002)	8.5 (0.33) Int:102	DS	101.6 (4.0)	274	20	130	V-0	All	*	
<b>8G</b>	0.05 (0.002)	0.05 (0.002)	8.5 (0.33) Int:102	DS	50.8 (2.0)	274	20	130	V-0	All	*	
<b>8H</b>	0.05 (0.002)	0.05 (0.002)	17 (0.67) Int:102	DS	101.6 (4.0)	288	20	140	V-0	All	4	
<b>8I</b>	0.05 (0.002)	0.05 (0.002)	12 (0.47) Int:102	DS	76.2 (3.0)	274	20	130	V-0	All	3	
<b>Multilayer printed wiring boards, flammability only Recognition.</b>												
<b>8R</b>	-	-	-	DS	-	260	20	-	V-0	-	-	
<b>Single layer printed wiring boards.</b>												
<b>1C</b>	0.08 (0.003)	0.15 (0.006)	8.1 (0.32)	DS	76.2 (3.0)	274	20	130	V-0	All	3	
<b>1D</b>	0.05 (0.002)	0.15 (0.006)	8.1 (0.32)	DS	76.2 (3.0)	274	20	130	V-0	All	3	
<b>1E</b>	0.05 (0.002)	0.15 (0.006)	17.3 (0.68)	DS	76.2 (3.0)	274	20	130	V-0	All	-	
<b>1F</b>	0.05 (0.002)	0.05 (0.002)	8.5 (0.33)	DS	101.6 (4.0)	274	20	130	V-0	All	*	
<b>1I</b>	0.05 (0.002)	0.05 (0.002)	12 (0.47)	DS	76.2 (3.0)	274	20	130	V-0	All	3	
<b>1P</b>	0.17 (0.007)	0.15 (0.006)	34 (1.34)	DS	101.6 (4.0)	274	20	130	V-0	All	4	

\* - CTI PLC is marked on individual board.



Marking: Company name or trademark, , and type designation. May be followed by a suffix to denote factory identification.

[Last Updated](#) on 2012-01-12

The appearance of a company's name or product in this database does not in itself assure that products so identified have been manufactured under UL's Follow-Up Service. Only those products bearing the UL Mark should be considered to be Listed and covered under UL's Follow-Up Service. Always look for the Mark on the product.